


J:\Drawings\2010\103-87305 Electrolux Jefferson, Iowa\US_KProduction\10387305K001 Well Locations.dwg | Layout: Site | Modified: CSCHAEFER 09/15/2015 4:18 PM | Plotted: CSCHAEFER 09/23/2015



LEGEND

	Approximate Site Property Boundary
	Fence
	Edge of gravel
	Monitoring well location
	Deep monitoring well location (screened in yellow brown till)
	Deep monitoring well location (screened in dark gray till)
	Building
	Former Buildings (slab remains)
	Proposed Monitoring Well Location

NOTES

1.) BM #1 elev. = 1052.49 (NAVD 88) center top non-operating bolt on fire hydrant Northwest of main building.

2.) JEO consulting group did not find useful NGS monuments in the Jefferson area. A USGS 24,000k Topographic map elevation (1054.00) at the intersection of Mulberry Street and East Central Street as the assumed NAVD 88 elevation. This elevation agreed with the elevation generated from Geoid-09.

3.) The coordinates for this site are approximate Iowa State Plane North 1401 with a ground scale factor of 1.0000463418.

REFERENCES

Basemap taken from JEO Consulting Group, Inc. drawing titled, "Electrolux Home Products base map", dated 11/21/10, revised May 2012.

BUILDING DESCRIPTION

Building 1 constructed in 1960
Building 2 constructed in 1973
Building 3 constructed in 1992
Building 4 constructed in 1988
Addition 1 constructed in 1984
Addition 2 through addition 10 constructed in 1960

Building descriptions provided by Greene County Assessor's on-line database for the Jefferson site. (Property PIN# 008+11-05-400-003)

FIGURE NARRATIVE

This figure shows the former buildings and existing and proposed monitoring well locations at the former Electrolux Home Products facility in Jefferson, Iowa. The features shown on the concrete slab are locations of former concrete-lined floor pits and drains.

RCRA

555458

PROJECT			
ELECTROLUX HOME PRODUCTS JEFFERSON, IOWA			
TITLE			
PROPOSED MONITORING WELL LOCATIONS			
PROJECT No.	103-87305	FILE No.	10387305K001 Well Locations
DESIGN	JSP	09/15/2015	SCALE AS SHOWN
CADD	CDS	09/15/2015	FIGURE
CHECK			
REVIEW			
			1